UNCLASSIFIED

AD NUMBER

AD367517

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited


FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

THIS PAGE IS UNCLASSIFIED



BUREAU OF SHIPS GROUP TECHNICAL INSPECTION REPORT

CONFIDENTIAL Classification (Cascelled) (Changed to . Joint Chiefe of Staff (Action 15 Apr

U. S. GOVERNMENT AGENCIES MAY OBTAIN COPIES OF THIS REPORT DIRECTLY FROM DDC. OTHER QUALIFIED DDC USERS SHALL REQUEST THROUGH

> Director Defense Atomic Support Agency Washington, D. C. 20301 The company of the constant of


APPROVED:

CONFIDENTIAL.X. Forest, Captain, U.S.N.



reason to promise the constant of the constant

Page 1 of 31 Pages



TARI CE CONTENTS

	PAGE	ИО
Ship Characteristics Sheet	{	3
Midship Section	4	4
Overall Summary of Damage	- E	5
Hull Technical Inspection Report (Section I)	- 1	1
Machinery Tecinical Inspection Report (Section II)	- 1	6
Electrical Technical Inspection Report; (Section 111)	- 2	1
Photographic Section (Section IV)	- 2	7
Commending Officers Report	3	0

SECRET

USS LST 661

Page 2 of 31 Pages

U.S.S. LST 661

SHIP CHARACTERISTICS

Building Yard: American Bridge Co., Ambridge, Penna.

Commissioned: 28 April 1944.

HULL

Length Overall: 328 feet 0 inches.

Length on Waterline: 316 feet 0 inches

Beam (extreme): 50 feet 0 inches.

Drafts at time of test: Fwd. 5 feet 9 inches.

Aft. 11 feet 8 inches.

Limiting displacement: 4,080 tons.

Displacement at time of test: 3,278 tons.


MAIN PROPULSION PLANT

Main Engines: Two General Motors Diesels, type: 12 - 567 A. One per main shaft.
Reduction Gears: "Falk" - Single reduction. One per engine.
Propellers: Two are installed in ship.
Main Shafts: Two are installed in ship.
Ships Service Generators: Three - 100 KW.- 230 volts, D.C. units are installed.

SECRET

USS LST 661

Page 3 of 31 Pages



MIDSHIP SECTION **TEST**

B

SECRET

PAGE 4 OF 31

LST 661

9195

TECHNICAL INSPECTION REPORT

OVERALL SUMMARY

- I. Target Condition After Test.
- (a) Drafts after test, list, general areas of flooding, sources.

 There was no flooding, hence no change in drafts or list.
 - (b) Structural Damage.

HULL

None.

MACHINERY

No comment.

ELECTRICAL

There was no structural damage.

(c) Other damage.

HULL

Not observed.

MACHINERY

None.

ELECTRICAL

There was no damage to any electrical equipment.

SECRET

USS LST 661

Page 5 of 31 Pages

Π. Forces Evidenced and Effects Noted. (a) Heat. HULL None MACHINERY No evidence. ELECTRICAL There was no evidence of heat in way of electrical equipment. (b) Fires and Explosions. HULL None. MACHINERY No evidence. ELECTRICAL There were no fires or explosions in way of electrical equipment. (c) Shock. HULL None. MACHINERY No evidence. USS LST 661 SECRET Page 6 of 31 Pages

ELECTRICAL

There was no evidence of shock in way of electrical equipment.

(d) Pressure.

HULL

A temporary cargo hatch cover was installed to replace that burned in Test A. The canvas of the cover is disarranged and the wood is dislodged. This is apparently the result of blast or falling water.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of pressure in way of electrical equipment.

(e) Effects peculiar to the Atomic Bomb.

HULL

None.

MACHINERY

None, except radioactivity.

ELECTRICAL

Radioactivity in way of exposed equipment was the only effect noted peculiar to the Atom Bomb.

III. Results of Test on Target.

SEC1._T

USS LST 661

Page 7 of 31 Pages

(a) Effect on machinery, electrical, and ship control.

HULL

Not observed.

MACHINERY

The test had no effect on machinery, as far as could be determined by visual inspection. No machinery on this vessel was operated after Test B because of radioactivity, which was fairly high when the ship was inspected 18 days after Test B.

ELECTRICAL

No damage was apparent to electrical machinery or ship control.

(b) Effect on gunnery and fire control.

HULL

Not observed.

MACHINERY

No comment.

ELECTRICAL

No electrical damage affected gunnery or fire control.

(c) Effect on watertight integrity and stability.

HULL

None.

MACHINERY

No comment.

SECRET

USS LST 661

Page 8 of 31 Pages

ELECTRICAL

No electrical damage affected watertight integrity or stability.

(d) Effect on personnel and habitability.

HULL

None.

MACHINERY

None, except radioactivity.

ELECTRICAL

No electrical damage affected personnel or habitability.

(e) Effect on fighting efficiency.

HULL

The only effect on fighting efficiency would be that resulting from radiological contamination.

MACHINERY

None, except for possible effects of radioactivity. As the machinery was fully operable, the ship could probably have left the contaminated area without being seriously affected.

ELECTRICAL

No electrical damage affected the fighting efficiency of the vessel.

IV. Summary of Observer's Impressions and Conclusions.

HULL

No comment.

SECRET

USS LST 661

Page 9 of 31 Pages

MACHINERY

LST 661 was outside the range of physical damage from the explosion in Test ${\tt B}$.

ELECTRICAL

No damage was evident on any electrical equipment due to Test B. It appears that present electrical designs have sufficient shock resistance to withstand the effects of the Atom Bomb under conditions existing on this vessel during Test B.

V. Preliminary Recommendations.

HULL

None.

MACHINERY

None.

ELECTRICAL

None.

SECRET

USS LST 661

Page 10 of 31 Pages

TECHNICAL INSPECTION REPORT

SECTION I - HULL

GENERAL SUMMARY OF HULL DAMAGE

- I. Target Condition After Test.
 - (a) Drafts after test; list; general areas of flooding, sources.

There was no flooding, hence no change in drafts or list.

(b) Structural Damage.

None.

(c) Other damage.

Not observed.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

None

(b) Fires and Explosions.

None.

(c) Shock.

None.

(d) Pressure.

A temporary cargo hatch cover was installed to replace that burned in Test A. The canvas of the cover is disarranged SECRET USS LST-661

Page 11 of 31 Pages

and the wood is dislodged. This is apparently the result of blast or falling water.

(e) Effects peculiar to the Atom Bomb.

None.

- III. Effects of Damage.
 - (a) Effect on machinery, electrical, and ship control.

 Not observed.
 - (b) Effect on gunnery and fire control.

Not observed.

(c) Effect on watertight integrity and stability.

None.

(d) Effect on personnel and habitability.

None.

(e) Effect on fighting efficiency.

The only effect on fighting efficiency would be that resulting from radiological contamination.

IV. General Summary of Observers' Impressions and Conclusions.

No comment.

V. Preliminary General or Specific Recommendations of Inspection Group.

None.

SECRET

USS LST661

Page 12 of 31 Pages

VI. Instructions for loading the vessel specified the following:

Fuel oil
Diesel oil
Ammunition

LOADING

50 tons

Potable and reserve feed water 95% Salt water ballast 95%

Details of the actual quantities of the various items aboard are included in Report 7, Stability Inspection Report, submitted by the ship's force in accordance with "Instructions to Target Vessels for Tests and Observations by Ship's Force" issued by the Director of Ships Material. This report is available for inspection in the Bureau of Ships Crossroads Files.

SECRET

USS LST661

Page 13 of 31 Pages

DETAILED DESCRIPTION OF HULL DAMAGE

A. General Description of Hull Damage.

The temporary closure over the cargo hatch is dislodged. There is no other damage. General views of the ship are on pages 28 and 29.

B. Superstructure.

No damage.

C. Turrets, Guns, and Directors.

No damage.

D. Torpedo Mounts, Depth Charge Gear.

Not applicable.

E. Weather Deck.

The temporary closure over the cargo hatch is dislodged. There is no other damage.

F. Exterior Hull.

No damage.

G. Interior Compartments (above w.l.).

No damage.

H. Armor Decks and Miscellaneous Armor.

Not applicable.

I. Interior Compartments (below w.l.).

No damage.

SECRET

USS LST 661

Page 14 of 31 Pages

J. Underwater Hull.

No damage.

K. Tanks.

No damage.

L. Flooding.

None.

M. Ventilation.

No damage.

N. Ship Control.

No damage.

O. Fire Control.

No damage.

P. Ammunition Behavior.

No damage.

Q. Ammunition Handling.

No damage.

R. Strength.

No damage.

S. Miscellaneous.

No comment.

SECRET

USS LST661

Page 15 of 31 Pages

TECHNICAL INSPECTION REPORT

SECTION II - MACHINERY

GENERAL SUMMARY OF MACHINERY DAMAGE

- I. Target Condition After Test.
 - (a) Drafts after test; list; general areas of flooding sources.

 No data taken by machinery group.
 - (b) Structural damage.

No comment.

(c) Other damage.

None.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

No evidence.

(b) Fires and explosions.

No evidence.

(c) Shock.

No evidence.

(d) Pressure.

No evidence.

(e) Effects apparently peculiar to the atom bomb.

None, except radioactivity.

SECRET

USS LST 661

Page 16 of 31 Pages

III. Effects of Damage.

(a) Effect on machinery and ship control.

The test had no effect on machinery, as far as could be determined by visual inspection. No machinery on this vessel was operated after Test B, because of radioactivity, which was fairly high when the ship was inspected 18 days after Test B.

(b) Effect on gunnery and fire control.

No comment.

(c) Effect on water-tight integrity and stability.

No comment.

(d) Effect on personnel and habitability.

None, except radioactivity.

(e) Total effect on fighting efficiency.

None except for possible effects of radioactivity. As the machinery was fully operable, the ship could probably have left the contaminated area without being sericusly affected.

IV. General Summary.

LST 661 was outside the range of physical damage from the explosion in Test B.

V. Preliminary Recommendations.

None.

SECRET

USS LST 661

Page 17 of 31 Pages

DETAILED DESCRIPTION OF MACHINERY DAMAGE

- A. General Description of Machinery Damage.
 - (a) Overall condition.

The overall condition of the machinery was not changed by Test B.

(b) Areas of major damage.

None.

(c) Primary cause of damage in each area of major damage.

Not Applicable.

(d) Effect of target test on overall operation of machinery plant.

Test B had no effect on operation of the machinery as far as can be determined by visual inspection. No machinery on this vessel was operated after Test B.

B. Boilers.

No apparent damage.

C. Blowers.

No apparent damage.

D. Fuel Oil Equipment.

No apparent damage.

E. Boiler Feedwater Equipment.

No apparent damage.

SECRET

USS LST 661

Page 18 of 31 Pages

No apparent damage.

G. Reduction Gears.

No apparent damage.

H. Shafting and Bearings.

No apparent damage.

I. Lubrication System.

No apparent damage.

J. Condensers and Air Ejectors.

Not Applicable.

K. Pumps.

No apparent damage.

L. Auxiliary Generators (Turbines and Gears).

Not Applicable.

M. Propellers.

Not inspected. The propellers could not be examined from the surface of the water. There is no reason to believe that they were damaged.

N. Distilling Plant.

No apparent damage.

SECRET USS LST 661

Page 19 of 31 Pages

O. Refrigeration Plant.

No apparent damage.

P. Winches, Windlasses, and Capstans.

No apparent damage.

Q. Steering Engine.

No apparent damage.

R. Elevators, Ammunition Hoists, Etc..

No apparent damage.

S. Ventilation (Machinery).

No apparent damage.

T. Compressed Air Plant.

No apparent damage.

U. Diesels (Generators and Boats).

No apparent damage.

V. Piping Systems.

No apparent damage.

W. Miscellaneous.

No apparent damage.

SECRET

USS LST 661

Page 20 of 31 Pages

TECHNICAL INSPECTION REPORT

SECTION III - ELECTRICAL

GENERAL SUMMARY OF ELECTRICAL DAMAGE

- I. Target Condition After Test.
 - (a) Drafts after test; list; general areas of flooding, sources.
 - 1. Drafts and list were the same as before the test.
 - 2. There was no flooding.
 - (b) Structural damage.

There was no structural damage.

(c) Other damage.

There was no damage to any electrical equipment.

- II. Forces Evident and Effects Noted.
 - (a) Heat.

There was no evidence of heat in way of electrical equipment.

(b) Fires and explosions.

There were no fires or explosions in way of electrical equipment.

(c) Shock.

There was no evidence of shock in way of electrical equipment.

SECRET

LST 661

Page 21 of 31 Pages

There was no evidence of pressure in way of electrical equipment.

(e) Effects peculiar to the Atom Bomb.

Radioactivity in way of exposed equipment was the only effect noted peculiar to the Atom Bomb.

III. Effects of Damage.

- (a) Effect on electrical machinery and ship control.

 No damage was apparent to electrical machinery or ship control.
 - (b) Effect on gunnery and fire control.

 No electrical damage affected gunnery or fire control.
- (c) Effect on watertight integrity and stability.

 No electrical damage affected watertight integrity or stability.
- (d) Effect on personnel and habitability.

 No electrical damage affected personnel or habitability.
 - (e) Effect on fighting efficiency.

No electrical damage affected the fighting efficiency of the vessel.

IV. General Summary of Observers Impressions.

No damage was evident on any electrical equipment due to test Baker. It appears that present electrical designs have

SECRET LST 661

Page 22 of 31 Pages

sufficient shock resistance to withstand the effects of the Atom Bomb under conditions existing on this vessel during Test.

V. Recommendations.

None.

SECRET LST 661

Page 23 of 31 Pages

- A. General Description of Electrical Damage.
 - (a) Overall condition.

The overall condition of the electric plant is the same as before the test.

- (b) Areas of major damage.

 None.
- (c) Primary causes of damage in each area of major damage.

 None.
- (d) Effect of target test on overall operation of electric plant.
 - 1. Ship's service generator plant: No effect.
 - 2. Engine and boiler auxiliaries: No effect.
 - 3. Electric propulsion: Not applicable.
 - 4. Communications: No effect.
 - 5. Fire control circuits: No effect.
 - 6. Ventilation: No effect.
 - 7. Lighting: No effect.
 - (e) Types of equipment most affected.

 None.
- B. Electric Propulsion Rotating Equipment.

Not applicable.

SECRET LST 661

Page 24 of 31 Pages

C. Electric Propulsion Control Equipment.

Not applicable.

D. Ship's Service Generators.

No damage.

E. Emergency Generators.

Not applicable.

F. Switchboards, Distribution and Transfer Panels.

No damage.

G. Wiring, Wiring Equipment and Wireways.

No damage.

H. Transformers.

No damage.

I. Submarile Propelling Batteries.

Not applicable.

J. Portable Batteries.

No damage.

K. Motors, Motor Generator Sets and Motor Controllers.

No damage.

L. Lighting Equipment.

No damage.

SECRET

LST 661

Page 25 of 31 Pages

No damage.

N. Degaussing Equipment.

No damage.

O. Gyro Compass Equipment.

No damage.

P. Sound Powered Telephones.

No damage.

Q. Ship's Service Telephones.

Not applicable.

R. Announcing Systems.

No damage.

S. Telegraphs.

No damage.

·T. Indicating Systems.

No damage.

U. I. C. and A. C. O. Switchboards.

Not applicable.

V. F. C. Switchboards.

Not applicable.

SECRET

LST 661

Page 26 of 31 Pages

SECTION IV

PHOTOGRAPHS

TEST BAKER

SECRET

USS LST 661

Page 27 of 31 Pages




AB-CR-227-289-141. View from off starboard low after Test B.

SECRET

Page 28 of 31 Pages

USS LST-661

9195



AB-CR-227-289-145. View from off port quarter after Test B.

SECRET

Page 29 of 31 Pages

USS LST-661 9195

APPENDIX

COMMANDING OFFICERS REPORT

TEST BAKER

SECRET

USS LST 661

Page 30 of 31 Pages

COMMANDING OFFICERS REPORT

REPORT # 5

SECTION I

Initial inspection of the LST 661 was accomplished on 13 August 1946.

No Material damage was found or evident thereof which was caused by Test B.

No equipment was operated or energized.

SECRET

USS LST 661

Page 31 of 31 Pages



Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 ₩	XRD-203-Section 12✓
AD-366589	XRD-200-Section 9
AD-366590 L	XRD-204-Section 13
AD-366591	XRD-183
✓ AD-366586 ২	XRD-201-Section 10
∠AD-367487.℃	XRD-131-Volume 2-
✓AD-367516¥	XRD- ₹ 143 ✓
✓AD-367493 ്	XRD-142 ►
AD-801410L 🗸	XRD-138
AD-376831L 🗸	XRD-83
AD-366759	XRD-80
✓AD-376830L ❖	XRD-79 ✓
✓AD-376828L 🌂	XRD-76✓
∠ AD-367464. ×	XRD-106 ✓
AD-801404L	XRD-105-Volume 1
✓AD-367459 🕱	XRD-100✓

TRC

Subject: Declassification of Reports

т (assilication of i	«еротев	
	AD-367517 🔾	XRD-141 ✔	
	AD-366762 ▶	XRD-84	
	AD-366760	XRD-81	
	AD-366761	XRD-82	
	AD-367501 ✓	XRD-158-Volume	1
	AD-367507L 🗸	XRD-152-Volume	4
	AD-367495 🖟	XRD-184⊁	
	AD-367485 🕊	XRD-129 ≻	
	AD-367484 🚜	XRD-128 ✓	
	AD-367483 🔏	XRD-127 ₽	
	AD-367482 X	XRD-126 ►	
	AD-367488 ►	XRD-132	
	AD-367480 🗡	XRD-124~	
	AD-801409L ✓	XRD-135	
	AD-367490 💘	XRD-136 ⊬	
	AD-367492 💢	XRD-137►	
	AD-801411L 🗸	XRD-139	
	AD-367518 🗶	XRD-140 ✓	
	AD-367515 ✔	XRD-144	
	AD-367514 ✔	XRD-145	
	AD-367468 🔏	XRD-110-Volume	2 V
	AD-367513✔	XRD-146	
	AD-367497 X	XRD-162	

Subject: Declassification of Reports

AD-801406L ✓ XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

Sondith Janets ARDITH JARRETT

Chief, Technical Resource Center